

**PLEASANTON**  
UNIFIED SCHOOL DISTRICT

**FACILITIES MASTER PLAN 2022**  
PLEASANTON UNIFIED SCHOOL DISTRICT

SITE FUNCTIONALITY ASSESSMENT

# VALLEY VIEW ELEMENTARY SCHOOL



**Site Functionality Assessment**

**VALLEY VIEW ELEMENTARY SCHOOL**

**SITE DATA**



**Valley View Elementary School**

480 Adams Way  
Pleasanton, Ca 94566

Current Enrollment (2021/22): 582  
Grades Served: TK-5

Original Construction Date: 1959  
Various Renovations: 1964-2006  
Number of Portable Classrooms: 2

Measure II Improvements:

- Fire alarm system upgrades
- Site security fencing
- Security cameras
- VOIP and clock speaker system
- Exterior site lighting
- Security system upgrade
- Telecom infrastructure upgrade
- HVAC
- Roofing
- Water efficient toilets and fountains
- Classroom technology
- Paint (summer 2022)

**PRINCIPAL SURVEY**

Top Priorities:

1. Lunch shelter
2. Resurface and restripe the hardcourts
3. Toileting for TK and Kindergarten

**SITE USE AND FUNCTIONALITY**

Valley View Elementary is a dual-language immersion school of English and Spanish. Currently, the grade levels are organized as the following per grade level:

- Kindergarten through 3<sup>rd</sup>:
  - three (3) dual language classes
  - two (2) English-only classes
- 4<sup>th</sup> and 5<sup>th</sup>:
  - two (2) dual language classes
  - two (2) English-only classes

**General Education Classrooms**

Classrooms are organized along double-loaded interior corridors that are used for organized storage and pull-out services.

Classrooms have a teaching wall, other built-in casework for storage, and a sink area. Students have individual desks and chairs. Technology includes a mobile LCD monitor. Backpack hooks are available along the exterior wall of the classroom.

Not all TK/Kindergarten classrooms have interior restrooms. Students within those classrooms use restrooms at the end of the shared hallway.

**Special Education Classrooms**

This site does not currently house SDC classes.

**Student Services / Counseling**

The Speech pathologist has a small office. The principal notes that a larger space is desired. The intervention room is housed in the site's old computer lab and is shared by multiple specialists. Ideally, the principal would like each specialist to have their own acoustically-separated space to reduce interference between groups.

**Staff and Administrative Spaces**

The site has a spacious front office. The principal notes that additional access point(s) to the Faculty Lounge is desired.

**Kitchen / Cafeteria / Food Service**

The kitchen is located within the Multi-Purpose Room. An interior serving area is also located at the MPR/Kitchen. The principal notes that the serving line is very narrow and would like it widened.

Students dine outside, at tables with umbrellas. A lunch shelter is desired for this area.

**Student Assembly**

The MPR has in-wall tables and two (2) retractable basketball hoops and backstops. Presentation technology is mobile, speakers are wall-mount.

This site does not have a permanent stage. A temporary stage is stored in a room of the MPR building.

**Library**

The Library is a spacious room with book stacks lining the perimeter with additional, low book shelving available. There is a 'book nook' area of



PROCESS



PLANNING



VISION



## Site Functionality Assessment

## VALLEY VIEW ELEMENTARY SCHOOL

### SITE USE AND FUNCTIONALITY, continued

lowered ceiling, shelving, and a rug. The Library space is furnished with traditional tables and chairs. Students can access computer stations. Presentation technology includes a ceiling-mount projector and drop-down screen as well as a mobile LCD monitor.

### *Outdoor Play Equipment / Playfields / Hardcourts*

The Kindergarten play structure is fairly new, in good condition, and has rubber surfacing. The lower and upper primary play structures are also noted by the principal to be in good condition and have bark mulch on the groundplane.

The principal notes that the hardcourts need to be resurfaced and new striping painted.

Kids Club utilizes the Kindergarten play yard.

The garden is in need of improvement.

### *Specialized Elective Spaces*

Music is occupying an at-grade modular classroom. The placement of this classroom creates line-of-sight difficulties at the hardcourts.

The Computer Lab had been underutilized and is now housing the intervention programs.

The Science / Exploration Lab is located next to the intervention room. This space has a teaching wall, perimeter casework with two (2) sinks, and built-in kitchenette with oven, stove, microwave, refrigerator, and a dishwasher. Furniture within this room is comprised of science-grade tables and stools. The room is equipped with a mobile LCD monitor and ceiling-mount projector with drop-down screen at the teaching wall.

### *Restrooms*

Not all TK/Kindergarten classrooms have attached restrooms.

### *Site / Parking / Drop-Off*

The site utilizes the drop-off loop at the front of campus. Parking is adequate for staff and visitors.

### *Technology*

Classroom technology has been upgraded with a mobile LCD monitor.





PROCESS



PLANNING



VISION



SITES

**Site Functionality Assessment**

**VALLEY VIEW ELEMENTARY SCHOOL**



Shade Structure



Drop-Off Lane / Parking



Site Identification and Announcements



Play Structure



Hardcourts



Site Artwork



Faculty Lounge



Administration Office



Quad





PROCESS



PLANNING



VISION



SITES

**Site Functionality Assessment**

**VALLEY VIEW ELEMENTARY SCHOOL**



Typical Classroom



Interior Hallway and Pull-Out Tables



Kindergarten Classroom



Student Services / Counseling




Multi-Purpose Room



Exploration Room



Library



Food Service: Serving Area



Student Dining Area



## Existing Site Plan | VALLEY VIEW ELEMENTARY SCHOOL



**Classrooms**  
# Indicates Grade Level  
K Kindergarten

**Electives / Labs**  
CL Computer Lab  
MU Music Room  
SCI Science Lab

**Shared Spaces**  
MPR Multi-Purpose Room  
LIB Library  
SERV Serving Area (Food Service)

**Student Services**  
INT Intervention  
RSP Resource Specialist


**Admin / Faculty**  
CO Conference  
FL Faculty Lounge  
FW Faculty Workroom  
H Health Room  
KIT Kitchen (Food Service)  
M Main Office / Front Desk  
O Office  
WR Satellite Faculty Workroom

**Leased Spaces / Other**  
KC Kids Club

**Support Spaces**  
ST Storage  
T Toilet/Restroom  
U Utility  
C Custodian

★ Main Entry  
→ Drop-Off  
□ LS - Lunch Shelter  
□ Portable Classrooms

<b>Teaching Stations:</b>	
PS (Preschool)	0
TK (Transitional Kinder)	1
Kindergarten	4
Grades 1-3	16
Grades 4-5	8
SDC mild/mod	0
SDC mod/sev	0
<b>Sub-Total:</b>	<b>29</b>
<b>Additional Spaces:</b>	
Exploration Lab / Music / Art	3
After School Care	1
<b>Total:</b>	<b>33</b>





## Proposed Master Plan Diagram | VALLEY VIEW ELEMENTARY SCHOOL



No Work
  Modernization
  Reconfiguration
  New Construction

**Classrooms**

- # Indicates Grade Level
- TK Transitional Kindergarten
- K Kindergarten
- SDC Special Education
- M/M Mild/Moderate
- M/S Moderate/Severe

**Electives / Labs**

- EXP Exploration Lab
- FLEX Flex Lab
- MU Music Room

**Shared Spaces**

- MPR Multi-Purpose Room
- LIB Library
- SERV Serving Area (Food Service)

**Student Services**

- LC Learning Center
- RSP Resource Specialist

**Admin / Faculty**

- CO Conference
- FL Faculty Lounge
- FW Faculty Workroom
- H Health Room
- KIT Kitchen (Food Service)
- M Main Office / Front Desk
- O Office
- WR Satellite Faculty Workroom

**Leased Spaces / Other**

- KC Kids Club

**Support Spaces**

- ST Storage
- T Toilet/Restroom
- U Utility
- C Custodian

Main Entry
  New Fencing  
 Drop-Off

Teaching Stations:	
PS (Preschool)	0
TK (Transitional Kinder)	5
Kindergarten	5
Grades 1-3	12
Grades 4-5	7
SDC mild/mod	0
SDC mod/sev	1
<b>Sub-Total:</b>	<b>30</b>
Additional Spaces:	
Exploration Lab / Music / Art	3
After School Care	1
<b>Total:</b>	<b>34</b>



Master Plan Cost Estimate

VALLEY VIEW ELEMENTARY SCHOOL

TOTAL PROGRAM COST  
(2022\$)

1. Site-Wide: Deferred Maintenance	\$	6,408,000
2. Modernize & Reconfigure Classrooms	\$	2,010,000
3. Classrooms: New Construction	\$	19,230,000
4. Transitional Kindergarten	\$	7,341,000
5. Science & Electives Spaces	\$	5,047,000
6. Visual & Performing Arts	\$	-
7. Multi-Purpose Room & Food Service	\$	3,601,000
8. Library	\$	699,000
9. Student Support & Counseling Services	\$	2,533,000
10. Administration & Staff Support	\$	2,062,000
11. Physical Education Facilities	\$	-
12. Building Systems: Restrooms & HVAC	\$	1,479,000
13. Site Utilities	\$	184,000
14. Safety & Security	\$	270,000
15. Campus Arrival	\$	1,523,000
16. Outdoor Learning	\$	791,000
17. Exterior Play Spaces	\$	2,379,000
18. Flexible Furniture	\$	1,225,000
	<b>\$</b>	<b>56,782,000</b>

Total project cost includes construction costs and soft costs (design) for the scope of work identified.

The following items are excluded from this budget:

- utility hook-up fees and city connections
- off-site work
- land acquisition costs
- hazardous material surveys, abatement, and disposal
- escalation (all costs are in 2022 dollars)
- temporary housing brought in during construction



# FACILITY CONDITION ASSESSMENT



**BUREAU  
VERITAS**

*prepared for*

**Pleasanton Unified School District**  
4750 First Street  
Pleasanton, California 94566



Valley View Elementary School  
480 Adams Way  
Pleasanton, California 94566

**PREPARED BY:**

*Bureau Veritas  
10461 Mill Run Circle, Suite 1100  
Owings Mills, Maryland 21117  
800.733.0660  
[www.us.bureauveritas.com](http://www.us.bureauveritas.com)*

**BV CONTACT:**

*Matt Anderson  
Program Manager  
800.733.0660 x7613  
[Matt.anderson@bureauveritas.com](mailto:Matt.anderson@bureauveritas.com)*

**BV PROJECT #:**

*151464.21R000-007.017*

**DATE OF REPORT:**

*January 4, 2022*

**ON SITE DATE:**

*December 8, 2021*

**Bureau Veritas**

# TABLE OF CONTENTS

- 1. Executive Summary ..... 1**
  - Campus Overview and Assessment Details ..... 1
  - Campus Findings and Deficiencies ..... 2
  - Facility Condition Index (FCI) ..... 3
  - Immediate Needs..... 6
  - Key Findings ..... 7
  - Plan Types..... 9
- 2. Administration/Library/Classrooms ..... 10**
- 3. Kid’s Club ..... 12**
- 4. Mulitpurpose Room ..... 14**
- 5. Northeast Classrooms ..... 16**
- 6. South Classrooms ..... 18**
- 7. Site Summary ..... 20**
- 8. Property Space Use and Observed Areas ..... 21**
- 9. ADA Accessibility ..... 22**
- 10. Purpose and Scope ..... 24**
- 11. Opinions of Probable Costs ..... 26**
  - Methodology ..... 26
  - Definitions ..... 26
- 12. Certification ..... 28**
- 13. Appendices ..... 29**





# 1. Executive Summary

---

## Campus Overview and Assessment Details

General Information	
<b>Property Type</b>	Elementary School
<b>Number of Buildings</b>	11
<b>Main Address</b>	480 Adams Way, Pleasanton, California 94566
<b>Site Developed</b>	1959 Renovated 1964 - 2006
<b>Site Area</b>	9.0 acres (estimated)
<b>Parking Spaces</b>	111 total spaces all in open lots; 4 of which are accessible
<b>Leased Spaces</b>	None
<b>Date(s) of Visit</b>	December 8, 2021
<b>On-site Point of Contact (POC)</b>	John Harshbarger
<b>Assessment and Report Prepared By</b>	Justin Vang
<b>AssetCalc Link</b>	Full dataset for this assessment can be found at: <a href="https://www.assetcalc.net/">https://www.assetcalc.net/</a>

## Campus Findings and Deficiencies

### Historical Summary

The school was originally developed in 1959. Additional buildings continued to be constructed until 2006. Major renovations and modernization occurred in 1998.

### Architectural

Most of the buildings consist of light gauge steel construction. Some classrooms are modular building with modular construction and metal roof. In general, the structures appear to be sound, with no significant areas of settlement or structural-related deficiencies observed. Finishes are anticipated for lifecycle replacement based on useful life and normal wear.

### Mechanical, Electrical, Plumbing and Fire (MEPF)

The MEPF infrastructure itself is generally in good working condition with no major expenditures anticipated in the short term. The HVAC systems generally consist of packaged units and some exhaust fans and are replaced as needed. In general, the plumbing systems are adequate to serve the facilities, with equipment and fixtures updated as needed. Electrical service equipment and systems are anticipated for lifecycle replacement. The facilities are protected by a hard-wired fire alarm system.

### Site

In general, the sites have been well maintained. The majority of the sites contain moderate to heavy landscaping, which are served by in-ground irrigation systems. The asphalt paved parking areas and drive aisles are well maintained as a result of frequent sealing and striping.

### Recommended Additional Studies

The ceilings in multiple areas are in poor condition due to water damage which may be from the packaged units on the roof. A professional engineer must be retained to analyze the existing condition, provide recommendations and, if necessary, estimate the scope and cost of any required repairs. The cost of this study is included in the cost tables. A budgetary cost allowance to replace the ceiling is also included.

Some areas of the facility were identified as having major or moderate accessibility issues. Bureau Veritas recommends a study be performed to take measurements, provide additional itemized details, research local requirements, and, if necessary, estimate the scope and cost of any required improvements. The cost of this study is included in the cost tables. Due to the lack of measurements and itemized findings at this point in time, the costs for any possible subsequent repairs or improvements are not currently included.

## Facility Condition Index (FCI)

One of the major goals of the FCA is to calculate each building's Facility Condition Index (FCI), which provides a theoretical objective indication of a building's overall condition. By definition, the FCI is defined as the ratio of the cost of current needs divided by current replacement value (CRV) of the facility. The chart below presents the industry standard ranges and cut-off points.

FCI Ranges and Description	
<b>0 – 5%</b>	In new or well-maintained condition, with little or no visual evidence of wear or deficiencies.
<b>5 – 10%</b>	Subjected to wear but is still in a serviceable and functioning condition.
<b>10 – 30%</b>	Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life.
<b>30% and above</b>	Has reached the end of its useful or serviceable life. Renewal is now necessary.

The deficiencies and lifecycle needs identified in this assessment provide the basis for a portfolio-wide capital improvement funding strategy. In addition to the current FCI, extended FCI's have been developed to provide owners the intelligence needed to plan and budget for the "keep-up costs" for their facilities. As such the 3-year, 5-year, and 10-year FCI's are calculated by dividing the anticipated needs of those respective time periods by current replacement value. As a final point, the FCI's ultimately provide more value when used to relatively compare facilities across a portfolio instead of being over-analyzed and scrutinized as stand-alone values. The table below summarizes the individual findings for this FCA:

Facility (year built)	Cost/SF	Total SF	Replacement Value	Current	3-Year	5-Year	10-Year
Administrative/Library/Classrooms (1959)	\$780	13,000	\$10,140,000	0.1%	0.8%	7.0%	15.3%
Kid's Club (KC) (1959)	\$780	1,000	\$780,000	0.0%	1.5%	2.4%	9.9%
Multipurpose Room (MPR) (1959)	\$780	5,300	\$4,134,000	0.0%	2.8%	6.8%	11.6%
Northeast Classrooms (1959)	\$780	9,500	\$7,410,000	0.0%	2.4%	10.7%	16.9%
South Classrooms (1959)	\$780	11,500	\$8,970,000	0.0%	1.5%	6.8%	10.8%



### Campus Level FCI:

The vertical bars below represent the year-by-year needs identified for the entire campus. The orange line in the graph below forecasts what would happen to the campus FCI (left Y axis) over time, assuming zero capital expenditures over the next ten years. The dollar amounts allocated for each year (blue bars) are associated with the values along the right Y axis.


## Needs by Year with Unaddressed FCI Over Time

### FCI Analysis: Valley View Elementary School

Replacement Value: \$43,440,000

Inflation Rate: 3.0%

Average Needs per Year: \$493,900



The table below shows the anticipated costs by trade or building system over the next 20 years.

<b>Systems Expenditure Forecast</b>						
<b>System</b>	<b>Immediate</b>	<b>Short Term (1-2 yr)</b>	<b>Near Term (3-5 yr)</b>	<b>Med Term (6-10 yr)</b>	<b>Long Term (11-20 yr)</b>	<b>TOTAL</b>
Structure	-	-	-	\$2,458	-	\$2,458
Facade	-	\$8,616	\$327,234	\$27,940	\$1,231,488	\$1,595,278
Roofing	-	\$9,930	\$691,342	\$22,898	-	\$724,170
Interiors	-	\$868	\$346,325	\$549,553	\$739,916	\$1,636,662
Plumbing	-	-	\$14,648	\$48,893	\$1,302,944	\$1,366,485
HVAC	-	\$479,121	\$63,649	\$21,409	\$417,275	\$981,454
Fire Protection	-	-	-	-	\$441,094	\$441,094
Electrical	-	-	\$352,527	\$646,409	\$1,319,736	\$2,318,672
Fire Alarm & Electronic Systems	-	-	\$106,811	\$378,375	\$166,409	\$651,595
Equipment & Furnishings	-	-	\$14,427	\$414,722	\$19,389	\$448,538
Special Construction & Demo	-	-	-	-	\$398,187	\$398,187
Site Development	-	-	\$89,545	\$446,130	\$54,197	\$589,872
Site Pavement	\$12,870	\$27,928	-	\$276,858	\$756,485	\$1,074,141
Site Utilities	-	-	-	\$42,305	-	\$42,305
Accessibility	\$8,775	-	-	-	-	\$8,775
<b>TOTALS</b>	<b>\$21,700</b>	<b>\$526,500</b>	<b>\$2,006,600</b>	<b>\$2,878,000</b>	<b>\$6,847,200</b>	<b>\$12,280,000</b>

## Immediate Needs

Facility/Building	Total Items	Total Cost
Administrative/Library/Classrooms	1	\$8,800
Site	1	\$12,900
<b>Total</b>	<b>2</b>	<b>\$21,700</b>

### Administrative/Library/Classrooms

ID	Location	Location Description	UF Code	Description	Condition	Plan Type	Cost
3517674	Valley View Elementary School / Administrative/Library /Classrooms	Throughout School	Y1090	ADA Miscellaneous, Level III Study, Includes Measurements, Evaluate/Report	NA	Accessibility	\$8,800
<b>Total (1 items)</b>							<b>\$8,800</b>

### Site

ID	Location	Location Description	UF Code	Description	Condition	Plan Type	Cost
3490029	Valley View Elementary School / Site	Site	G2020	Parking Lots, Pavement, Asphalt, Cut & Patch	Poor	Performance/Integrity	\$12,900
<b>Total (1 items)</b>							<b>\$12,900</b>



## Key Findings



### Exterior Walls in Poor condition.

Wood Siding  
Multipurpose Room (MPR) Valley View  
Elementary School Building Exterior

Uniformat Code: B2010  
Recommendation: **Replace in 2023**

Priority Score: **89.8**

Plan Type:  
Performance/Integrity

Cost Estimate: \$1,200

\$\$\$\$

Wood siding is very weathered. - AssetCALC ID: 3489873



### Exterior Walls in Poor condition.

Wood Siding  
Northeast Classrooms Valley View Elementary  
School Building Exterior

Uniformat Code: B2010  
Recommendation: **Replace in 2023**


Priority Score: **89.8**

Plan Type:  
Performance/Integrity

Cost Estimate: \$1,200

\$\$\$\$

Wood siding is weathered and deteriorating along building perimeter. - AssetCALC ID: 3489988



### Exterior Walls in Poor condition.

Wood Siding  
Administrative/Library/Classrooms Valley View  
Elementary School Building Exterior

Uniformat Code: B2010  
Recommendation: **Replace in 2024**


Priority Score: **89.7**

Plan Type:  
Performance/Integrity

Cost Estimate: \$1,200

\$\$\$\$

Wood siding along building perimeter has deterioration that may lead to water infiltration and more serious damage. - AssetCALC ID: 3489882



### Exterior Walls in Poor condition.

Stucco  
Multipurpose Room (MPR) Valley View  
Elementary School Building Exterior

Uniformat Code: B2010  
Recommendation: **Replace in 2024**

Priority Score: **89.7**

Plan Type:  
Performance/Integrity

Cost Estimate: \$4,700

\$\$\$\$

Stucco has damage from a drain spout. - AssetCALC ID: 3489842



**Roofing in Poor condition.**

Modified Bitumen  
 Multipurpose Room (MPR) Valley View  
 Elementary School Roof

Uniformat Code: B3010  
 Recommendation: **Replace in 2024**

Priority Score: **88.7**

Plan Type:  
 Performance/Integrity

Cost Estimate: \$9,400

\$\$\$\$

Roof has water accumulation that may be causing damage to ceiling tiles. - AssetCALC ID: 3489974



**Parking Lots in Poor condition.**

Pavement, Asphalt  
 Site Valley View Elementary School Site

Uniformat Code: G2020  
 Recommendation: **Cut & Patch in 2022**


Priority Score: **84.9**

Plan Type:  
 Performance/Integrity

Cost Estimate: \$12,900

\$\$\$\$

Asphalt is cracked and worn in various locations. - AssetCALC ID: 3490029



**Suspended Ceilings in Poor condition.**

Hard Tile, Replacement w/ ACT  
 Multipurpose Room (MPR) Valley View  
 Elementary School Throughout building

Uniformat Code: C1070  
 Recommendation: **Replace in 2024**


Priority Score: **81.7**

Plan Type:  
 Performance/Integrity

Cost Estimate: \$800

\$\$\$\$

Ceiling has water damage. - AssetCALC ID: 3489880



**Fire Suppression System**

Full System Install/Retrofit, Medium  
 Density/Complexity  
 Multipurpose Room (MPR) Valley View  
 Elementary School Throughout building

Uniformat Code: D4010  
 Recommendation: **Install in 2041**

Priority Score: **60.0**

Plan Type:  
 Retrofit/Adaptation

Cost Estimate: \$35,100

\$\$\$\$

No system currently exists. - AssetCALC ID: 3489879




## Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance.

### Plan Type Descriptions

<b>Safety</b>	■	An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk.
<b>Performance/Integrity</b>	■	Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability.
<b>Accessibility</b>	■	Does not meet ADA, UFAS, and/or other handicap accessibility requirements.
<b>Environmental</b>	■	Improvements to air or water quality, including removal of hazardous materials from the building or site.
<b>Retrofit/Adaptation</b>	■	Components, systems, or spaces recommended for upgrades in in order to meet current standards, facility usage, or client/occupant needs.
<b>Lifecycle/Renewal</b>	■	Any component or system that is not currently deficient or problematic but for which future replacement or repair is anticipated and budgeted.

### Plan Type Distribution (by Cost)



10-YEAR TOTAL: \$5,432,700