











Site Functionality Assessment

WALNUT GROVE ELEMENTARY SCHOOL

SITE DATA



Walnut Grove Elementary School

1999 Harvest Rd. Pleasanton, Ca 94566

Current Enrollment (2021/22): 582 Grades Served: TK-5

Original Construction Date: 1966 MPR Construction Date: 1997 Modernization: 2002

Number of Portable Classrooms: 2

Measure I1 Improvements:

- Fire alarm system upgrades
- Site security fencing
- · Security cameras
- VOIP and clock speaker system
- Security system upgrade
- Telecom infrastructure upgrade
- Roofing
- Water efficient toilets and fountains
- Classroom technology

PRINCIPAL SURVEY

Top Priorities:

- 1. Create a single point of entry
- 2. Lunch shelter
- Outdoor lawn areas (change to synthetic turf for Kindergarten and upper primary grades)

SITE USE AND FUNCTIONALITY

General Education Classrooms

Classrooms have a teaching wall, other built-in casework for storage, and a sink area. Students have individual desks and chairs. Technology includes a ceiling-mount projector with pull-down screen and a mobile LCD monitor. Backpack hooks are available along the exterior wall of the classroom.

Not all TK/Kindergarten classrooms have interior restrooms.

Special Education Classrooms

This site does not currently house SDC classes.

Student Services / Counseling

Speech and RSP share a classroom (separated by partitions) and would like acoustic separation. The principal would also like a space conducive to group sessions and suggests a lounge-style wellness center.

Staff and Administrative Spaces

The front of campus is clearly identified, however access to the Administration front office is unclear.

The Faculty Lounge is underutilized as a lounge, likely due to its lack of natural daylight.

Kitchen / Cafeteria / Food Service

The kitchen is located within the Multi-Purpose Room. Hot and cold food carts are set up near the kitchen for the student serving line.

Students dine at tables near the MPR. The principal would like a lunch shelter over this area.

Student Assembly

The MPR has in-wall tables and two (2) retractable basketball hoops and backstops. Presentation technology includes a mobile LCD monitor.

This site does not have a permanent stage. A temporary stage is stored in a room of the MPR building.

Library

The Library is a spacious room with tall book stacks lining the perimeter and creating aisles. The Library space is furnished with wood tables and chairs with some soft seating. Students can access computer stations. Presentation technology includes a wall-mount as well as a mobile LCD monitor.

Outdoor Play Equipment / Playfields / Hardcourts All play structures are fairly new, in good

condition, and has rubber surfacing.

The principal would like the grass areas of the K play yard and lower/upper primary play areas to be replaced with synthetic turf and address areas of poor drainage.











Site Functionality Assessment

WALNUT GROVE ELEMENTARY SCHOOL

SITE USE AND FUNCTIONALITY, continued

Specialized Elective Spaces

Music and Art are housed in portable classrooms located behind the MPR. These portables are quite far from the main campus.

The Computer Lab had been underutilized and is now used for storage. The principal would like to turn this area into a lounge-style project research space.

The Science / Exploration Lab is a spacious room located at the end of the upper primary grades wing. This space has a teaching wall, perimeter casework with sinks, and a storage room. Furniture within this room is comprised of science-grade tables and stools. The room is equipped with a mobile LCD monitor and ceilingmount projector with drop-down screen at the teaching wall.

Restrooms

Not all TK/Kindergarten classrooms have attached restrooms.

Site / Parking / Drop-Off

The site utilizes the drop-off loop at the front of campus. Parking is adequate for staff and visitors.

Technology

Classroom technology has been upgraded with a mobile LCD monitor.









Site Functionality Assessment

WALNUT GROVE ELEMENTARY SCHOOL



Shade Structure



Kindergarten Play Yard



Health Office



Drop-Off Lane / Parking



Hardcourts



Administration Office



Site Identification and Announcements



Play Structure



School Garden



PLEASANTON UNIFIED SCHOOL DISTRICT

FACILITIES MASTER PLAN









Site Functionality Assessment

WALNUT GROVE ELEMENTARY SCHOOL



Typical Classroom



Student Services / Counseling (RSP)



Library



Art Classroom



Multi-Purpose Room



Food Service: Kitchen



Kindergarten Classroom



Exploration Room



Student Dining Area









Classrooms

Indicates Grade Level Transitional Kindergarten Kindergarten

Electives / Labs

APE Adaptive PE
CL Computer Lab
MU Music Room SCI Science Lab

Shared Spaces
MPR Multi-Purpose Room LIB Library

Student Services

INT Intervention PSY Psychologist
RSP Resource Specialist
SP Speech

Admin / Faculty

Faculty Lounge Faculty Workroom Health Room Kitchen (Food Service) Main Office / Front Desk Office WR Satellite Faculty Workroom

Leased Spaces / Other

EDCC Extended Day Child Care (Leased)

Support Spaces

Storage Toilet/Restroom Utility Custodian



Portable Classrooms

Teaching Stations:	
PS (Preschool)	0
TK (Transitional Kinder)	1
Kindergarten	4
Grades 1-3	14
Grades 4-5	8
SDC mild/mod	0
SDC mod/sev	0
Sub-Total:	24

Additional Spaces:

Tot	al:	29	
Aft	er School Care	2	
Exp	oloration Lab / Music / Art	6	

Existing Site Plan | WALNUT GROVE ELEMENTARY SCHOOL











Proposed Master Plan Diagram | WALNUT GROVE ELEMENTARY SCHOOL



Classrooms

Indicates Grade Level Transitional Kindergarten Kindergarten SDC: Special Education: M/M Mild/Moderate Moderate/Severe

Electives / Labs

EXP Exploration Lab FLEX Flex Lab MU Music Room

Shared Spaces

MPR Multi-Purpose Room SERV Serving Area (Food Service)

Student Services

LC Learning Center RSP Resource Specialist Speech

Admin / Faculty

Conference Faculty Lounge Faculty Workroom Health Room Kitchen (Food Service) Main Office / Front Desk Office WR Satellite Faculty Workroom

Leased Spaces / Other

EDCC Extended Day Child Care (Leased)

Support Spaces

Storage Toilet/Restroom Utility Custodian



Total:

Main Entry

• • • • New Fencing



Teaching Stations: PS (Preschool) TK (Transitional Kinder) Kindergarten Grades 1-3 Grades 4-5 SDC mild/mod	O 5 5 14 7
SDC mod/sev Sub-Total:	1 32
Additional Spaces:	
Exploration Lab / Music / Art	3
After School Care	2





Master Plan Cost Estimate

WALNUT GROVE ELEMENTARY SCHOOL









TOTAL PROGRAM COST (2022\$)

1. Site-Wide: Deferred Maintenance	\$ 6,310,000
2. Modernize & Reconfigure Classrooms	\$ 6,545,000
3. Classrooms: New Construction	\$ 2,696,000
4. Transitional Kindergarten	\$ 7,325,000
5. Science & Electives Spaces	\$ 2,452,000
6. Visual & Performing Arts	\$ -
7. Multi-Purpose Room & Food Service	\$ 3,436,000
8. Library	\$ 587,000
9. Student Support & Counseling Services	\$ 1,445,000
10. Administration & Staff Support	\$ 2,465,000
11. Physical Education Facilities	\$ -
12. Building Systems: Restrooms & HVAC	\$ 3,818,000
13. Site Utilities	\$ -
14. Safety & Security	\$ 257,000
15. Campus Arrival	\$ 112,000
16. Outdoor Learning	\$ 753,000
17. Exterior Play Spaces	\$ 1,243,000
18. Flexible Furniture	\$ 1,225,000

\$ 40,669,000

Total project cost includes construction costs and soft costs (design) for the scope of work identified.

The following items are excluded from this budget:

utility hook-up fees and city connections

- off-site work
- land acquisition costs
- hazardous material surveys, abatement, and disposal
- escalation (all costs are in 2022 dollars)
- temporary housing brought in during construction

FACILITY CONDITION ASSESSMENT

BUREAU VERITAS

prepared for

Pleasanton Unified School District 4750 First Street Pleasanton, California 94566



Walnut Grove Elementary School 1999 Harvest Road Pleasanton, California 94566

PREPARED BY:

Bureau Veritas 10461 Mill Run Circle, Suite 1100 Owings Mills, Maryland 21117 800.733.0660 www.us.bureauveritas.com

BV CONTACT:

Matt Anderson
Program Manager
800.733.0660 x7613
Matt.anderson@bureauveritas.com

BV PROJECT #:

151464.21R000-009.017

DATE OF REPORT:

January 3, 2021

ON SITE DATE:

December 7, 2021

TABLE OF CONTENTS

1.	Executive Summary	[,]
	Campus Overview and Assessment Details	
	Campus Findings and Deficiencies	2
	Facility Condition Index (FCI)	
	Immediate Needs	
	Key Findings	
	Plan Types	
2.	A - Modular Buildings	9
3.	B - Administration/Library Building	
4.	C - Multi Purpose Room	
5.	D - Portables	
6.	Site Summary	1
7.	Property Space Use and Observed Areas	18
8.	ADA Accessibility	19
9.	Purpose and Scope	2
10.	Opinions of Probable Costs	2
	. Methodology	
	Definitions	
11.	Certification	
	Appendices	2

1. Executive Summary

Campus Overview and Assessment Details

General Information	
Property Type	Elementary School
Number of Buildings	12
Main Address	1999 Harvest Road, Pleasanton, California 94566
Site Developed	1966 Multipurpose Room 1997 Renovated 2002
Site Area	11.0 acres (estimated)
Parking Spaces	90 total spaces all in open lots; eight of which are accessible
Leased Spaces	No space leased
Date(s) of Visit	December 7, 2021
On-site Point of Contact (POC)	Ben Kerr
Assessment and Report Prepared By	Kay van der Have
AssetCalc Link	Full dataset for this assessment can be found at: https://www.assetcalc.net/

Campus Findings and Deficiencies

Historical Summary

Walnut Grove Elementary School was originally built as an elementary school in 1966. It was a progressive "open space" school and included an administration/library building and seven classroom pods. The Multipurpose Room (MPR) building was added in 1997. In 2002 the administration/library building was remodeled and the pods were demolished and replaced with eight modular classroom buildings. Four portable classrooms are on the site, two at the north perimeter and two at the south perimeter. Pleasanton School District is responsible for the northern portables and E.D.C.C. is responsible for the southern portables.

Architectural

The Administration and MPR buildings are wood framed slab on grade construction. The factory built modular buildings are placed on perimeter footings with underfloor ventilation. The exterior envelope throughout consists of painted stucco, mostly aluminum frame windows and steel or wood exterior doors. The modular buildings and the MPR have flat roofs with modified bitumen roofing and asphalt shingles cover the gable roof on administration building. There were no reports or signs of water infiltration. Exterior finishes and roofs were replaced in 2002, and short term roof replacement is anticipated. The interior finishes have been periodically replaced as-needed.

Mechanical, Electrical, Plumbing and Fire (MEPF)

With one exception, MEFP systems date to the 2002 renovation. Most of the HVAC consists of roof mounted packaged units, short term replacement is anticipated. Electrical and plumbing systems are generally adequate to serve the school's needs with equipment and fixtures updated as needed. The electric room in the Administration building needs an air conditioner and is included in the immediate needs. Building Photovoltaic panels were added to the MPR roof in 2007. The entire campus has a WIFI system, a PA system, security cameras and occupancy sensors for the light fixtures only. Current plans for the school include improving the security system. Interior light fixtures are mostly fluorescent. Exterior light fixtures are LED.

All buildings are connected to a basic hard wired fire alarm system, upgrades are planned. Fire suppression is limited to fire extinguishers except for the soffits of the administration building, which are protected by fire sprinklers.

Site

The asphalt parking areas and several concrete walkways were redone in 2007, regular sealing and striping is anticipated.

Recommended Additional Studies

Some areas of the facility were identified as having major or moderate accessibility issues. Bureau Veritas recommends a study be performed to take measurements, provide additional itemized details, research local requirements, and, if necessary, estimate the scope and cost of any required improvements. The cost of this study is included in the cost tables. Due to the lack of measurements and itemized findings at this point in time, the costs for any possible subsequent repairs or improvements are not currently included.



Facility Condition Index (FCI)

One of the major goals of the FCA is to calculate each building's Facility Condition Index (FCI), which provides a theoretical objective indication of a building's overall condition. By definition, the FCI is defined as the ratio of the cost of current needs divided by current replacement value (CRV) of the facility. The chart below presents the industry standard ranges and cut-off points.


FCI Ranges and Description							
0 – 5%	In new or well-maintained condition, with little or no visual evidence of wear or deficiencies.						
5 – 10%	Subjected to wear but is still in a serviceable and functioning condition.						
10 – 30%	Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life.						
30% and above	Has reached the end of its useful or serviceable life. Renewal is now necessary.						

The deficiencies and lifecycle needs identified in this assessment provide the basis for a portfolio-wide capital improvement funding strategy. In addition to the current FCI, extended FCI's have been developed to provide owners the intelligence needed to plan and budget for the "keep-up costs" for their facilities. As such the 3-year, 5-year, and 10-year FCI's are calculated by dividing the anticipated needs of those respective time periods by current replacement value. As a final point, the FCI's ultimately provide more value when used to relatively compare facilities across a portfolio instead of being over-analyzed and scrutinized as stand-alone values. The table below summarizes the individual findings for this FCA:

Facility (year built)	Cost/SF	Total SF	Replacement Value	Current	3-Year	5-Year	10-Year
A - Modular Buildings (2002)	\$480	39,600	\$19,008,000	0.0%	9.5%	12.1%	16.6%
B - Administration Building (1966)	\$805	13,650	\$10,988,250	0.0%	3.8%	5.2%	6.1%
C - Multi Purpose Room (1997)	\$780	6,418	\$5,006,040	2.5%	5.9%	11.6%	16.0%
D - Portables (2001)	\$380	1,600	\$608,000	0.0%	3.6%	10.4%	12.7%

Campus Level FCI:

The vertical bars below represent the year-by-year needs identified for the entire campus. The orange line in the graph below forecasts what would happen to the campus FCI (left Y axis) over time, assuming zero capital expenditures over the next ten years. The dollar amounts allocated for each year (blue bars) are associated with the values along the right Y axis.



The table below shows the anticipated costs by trade or building system over the next 20 years.

System	Immediate	Short Term	Near Term	Med Term	Long Term	TOTAL
System	illillediate	(1-2 yr)	(3-5 yr)	(6-10 yr)	(11-20 yr)	TOTAL
Structure		13.7	120	(- ,- ,-,	4	
Facade	\$43,173	\$353,755	\$19,944	\$78,339	\$627,340	\$1,122,551
Roofing	()=	\$643,438	÷	\$10,898	\$173,732	\$828,068
Interiors	-	\$423,883	\$157,687	\$637,060	\$827,943	\$2,046,573
Plumbing	\$2,925	\$3,661	\$6,510	\$35,993	\$744,277	\$793,366
HVAC	\$78,975	\$36,989	\$479,813	\$9,159	\$247,983	\$852,919
Fire Protection	-		\$2,061	\$10,075	- 4	\$12,136
Electrical	-	\$135,544	\$548,050	\$7,174	\$546,515	\$1,237,283
Fire Alarm & Electronic Systems		\$53,621	\$276,664	\$42,016	\$216,914	\$589,215
Equipment & Furnishings	- 15	\$7,819	\$250,131	\$363,415	\$132,235	\$753,600
Special Construction & Demo		-			\$48,345	\$48,345
Site Utilities	-			\$61,063	\$29,123	\$90,186
Site Development	-	\$36,865	\$159,498	\$324,168	\$209,507	\$730,038
Site Pavement	-	\$17,593	-	\$20,396	\$51,054	\$89,043
Accessibility	\$8,775		. (4			\$8,775
TOTALS	\$133,900	\$1,713,200	\$1,900,400	\$1,599,800	\$3,855,000	\$9,202,300

Immediate Needs

Facility/Building	Total Items	Total Cost
A - Modular Buildings	1	\$8,800
C - Multi Purpose Room	.5	\$125,200
Total	6	\$134,000

A - Modular Buildings

ID	Location	UF Code	Description	Condition	Plan Type	Cost
3498763	Walnut Grove Elementary School / A - Modular Buildings	Y1090	ADA Miscellaneous. Level III Study, Includes Measurements, Evaluate/Report	Poor	Accessibility	\$8,800
Total (1 items)						\$8,800

C - Multi Purpose Room

ID	Location	UF Code	Description	Condition	<u>Plan Type</u>	Cost
3498817	Walnut Grove Elementary School / C - Multi Purpose Room	D3050	Packaged Unit, RTU, Pad or Roof- Mounted, Replace	Poor	Performance/Integrity	\$8,800
3498839	Walnut Grove Elementary School / C - Multi Purpose Room	D3050	Packaged Unit. RTU, Pad or Roof- Mounted 6 to 7.5 TON Replace	Failed	Performance/integrity	\$17,600
3498853	Walnut Grove Elementary School / C - Multi Purpose Room	D3050	Packaged Unit, RTU, Pad or Roof- Mounted, Replace	Poor	Performance/Integrity	\$52,700
3498805	Walnut Grove Elementary School / C - Multi Purpose Room	D2010	Sink/Lavatory Commercial Kitchen, 3-Bowl, Replace	Failed	Retrofit/Adaptation	\$2,900
3498856	Walnut Grove Elementary School / C - Multi Purpose Room	B2010	Exterior Walls, any surface, Clean	Poor	Performance/Integrity	\$43,200
Total (5 items)						\$125,200

Key Findings



Exterior Walls in Poor condition.

any surface C - Multi Purpose Room Walnut Grove Elementary School Building Exterior

Uniformat Code: B2010

Recommendation: Clean in 2022

Priority Score: 89.9

Plan Type:

Performance/Integrity

Cost Estimate: \$43,200

\$\$\$\$

Cleaning needed - AssetCALC ID: 3498856



Packaged Unit in Failed condition.

RTU, Pad or Roof-Mounted, 6 to 7.5 TON C - Multi Purpose Room Walnut Grove Elementary School Upper roof

Uniformat Code: D3050

Recommendation: Replace in 2022

Priority Score: 81.9

Plan Type:

Performance/Integrity

Cost Estimate: \$17,600

\$\$\$\$

Abandoned in place - AssetCALC ID: 3498839



Packaged Unit in Poor condition.

RTU, Pad or Roof-Mounted C - Multi Purpose Room Walnut Grove Elementary School Upper roof

Uniformat Code: D3050

Recommendation: Replace in 2022

Priority Score: 81.9

Plan Type:

Performance/Integrity

Cost Estimate: \$52,700

\$\$\$\$

These RTUs are worn out - AssetCALC ID: 3498853



Sink/Lavatory in Failed condition.

Commercial Kitchen, 3-Bowl C - Multi Purpose Room Walnut Grove Elementary School Kitchen

Uniformat Code: D2010

Recommendation: Replace in 2022

Priority Score: 56.9

Plan Type:

Retrofit/Adaptation

Cost Estimate: \$2,900

\$\$\$\$

A three compartment sink is code required, this one is only two - AssetCALC ID: 3498805



Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the "why" part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the "best" fit, typically the one with the greatest significance.

Plan Type Descriptions	
Safety	An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk.
Performance/Integrity	Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability.
Accessibility	Does not meet ADA, UFAS, and/or other handicap accessibility requirements.
Environmental	Improvements to air or water quality, including removal of hazardous materials from the building or site.
Retrofit/Adaptation	Components, systems, or spaces recommended for upgrades in in order to meet current standards, facility usage, or client/occupant needs.
Lifecycle/Renewal	Any component or system that is not currently deficient or problematic but for which future replacement or repair is anticipated and budgeted.

Plan Type Distribution (by Cost)

